2017-18

THIRD PARTY INSPECTION REPORT

Name of the Client: **Assistant Executive Engineer,** Dasarahalli Sub Division, BBMP, Bangalore.

Agency: **Technical Manager (West),** KRIDL, Bangalore.

Name of the Work: UGD Maintenance in Sidedahalli Village limit in Bagalagunte in Ward No.14 T.Dasarahalli Sub Division, BBMP, Bangalore.

THIRD PARTY CONSULTANTS

M/S. CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Road Materials Testing Laboratory)
An ISO 9001: 2008 Certified Company

#133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore-560056
e-mail: civilqualityconsultants@gmail.com Ph: 8553518550/9886998316

CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2008 Certified Company

JAS-ANZ
ISO 9001:2000 CERTIFIED

Name of Work: UGD Maintenance in Sidedahalli Village limit in Bagalagunte in Ward No.14 T.Dasarahalli Sub Division, BBMP, Bangalore.

Name of Client	:	**Assistant Executive Engineer,** Dasarahalli Sub Division, BBMP, Bangalore.
Contractor/Agency	:	**Technical Manager (West),** KRIDL, Bangalore.
Total Cost	:	Rs. 20.00 Lakhs
Date of Inspection	:	30.09.2017
In the Presence of	:	(a) **Assitant Engineer (W. No. 14),** BBMP, Bangalore.
	:	(b) **Mr. Mohan G**. Senior Engineer M/s Civil Quality Consultants And Engineeras, Bangalore.

3rd Party Compliance Report

Sl.No	Description of the Item		Comments / observations
1	Earthwork excavation for foundation of buildings, water supply, sanitary lines and electrical coduits either in pits or in trenches 1.5m....	:	Work done up to the billed quantity and Quality is satisfactory
2	Providing and laying in position to required level or slope 300mm internel diameter salt glazed stoneware pipe grade A and jointing with stiff mixture of cement mortar.....	:	Work done up to the billed quantity and Quality is satisfactory
3	Construction of brick masonry circular type manhole 0.91m internal dia at bottom 0.91m deep and 0.56m dia at top with table moulded non-modular bricks....	:	Work done up to the billed quantity and Quality is satisfactory
4	Providing and constructing burnt brick masonry with approved quality of non-modular bricks of standard size of class designation 50....	:	Work done up to the billed quantity and Quality is satisfactory
5	Providing 20mm thick cement plaster in single coat with cement mortar 1:4, to stone masonry including rounding off corners wherever required smooth rendering.....	:	Work done up to the billed quantity and Quality is satisfactory

QUALITY CONSULTANTS & ENGINEERS Bangalore

6	Providing and fixing SFRC Cover and frame 560mm (ID) Heavy Duty.. Material code No-0331...	:	Work done up to the billed quantity and Quality is satisfactory
7	Refilling available earth around pipe lines, cables in layers not exceeding 20cms in depth, compacting each deposited layer by ramming...	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಕೆ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Authorised Signatory
For CIVIL QUALITY CONCULTANTS & ENGINEERS

Authorised Signatory